



Please read this operating manual carefully. Correct assembly and handling of the tool will save you set-up time and allow you to achieve optimal results.

## KNUURLING PROFILES AND PRODUCTION PROCESS

Series 161 / 162	
Machining direction	Knurling profiles on the workpiece: RAA   RBL   RBR   RGE
radial / radial and axial	Selection of knurling wheels: 2 x AA   2 x BR   2 x BL   1 x BR   1 x BL

Table 1: Knurling profiles

Knurling profile	Manufacturing process	Knurling profile	Manufacturing process
RAA knurl with straight pattern	Knurling RAA Work-piece Knurling wheel AA	RBL left-hand knurl 30°/45°	Work-piece Knurling RBL 2x knurling wheel BR
RGE left-hand / right-hand knurling, Raised points, 30°/45°	Knurling RGE Work-piece 1x knurling wheel BL 1x knurling wheel BR	RBR right-hand knurl 30°/45°	Work-piece Knurling RBR 2x knurling wheel BL

Table 2: Manufacturing process

Designation	Torque	Pos. no.
M4 Allen screw	7 Nm	Fig. 1, pos. 7 Fig. 3, pos. 7
M8 Allen screw	28 Nm	Fig. 2, pos. 9 Fig. 4, pos. 10
M3 set screw	2 Nm	Fig. 1, pos. 9 Fig. 3, pos. 10
M4 set screw	7 Nm	Fig. 2, pos. 13, pos. 12 Fig. 4, pos. 11, pos. 12

Table 3: Torque specifications

## TOOL SETTING




Fig. 1: Series 161 Swiss typ turning lathe exploded drawing




Fig. 2: Series 161 CNC-lathe exploded drawing




Fig. 3: Series 162 Swiss typ turning lathe exploded drawing




Fig. 4: Series 162 CNC-lathe exploded drawing

### Ordering spare parts:

Please specify the tool number and the corresponding position number (see Fig. 1–4).

#### 1. Setting the centre height

The centre height is integrated in tool mount and corresponds to the upper shaft edge (Fig. 1–4, pos. 1).

#### 2. Knurling wheel assembly

For installation or replacement of knurling wheels, unscrew both threaded pins (Fig. 1, pos. 9; Fig. 2, pos. 13; Fig. 3, pos. 10; Fig. 4, pos. 11) and remove the axle pins (Fig. 1, pos. 4; Fig. 2, pos. 8) or collar studs (Fig. 3, pos. 6; Fig. 4, pos. 9). Then mount the new knurling wheel with the axle pins and/or collar studs and clamp with the threaded pin. Ensure that the axle pin is clamped on the planar surface.

#### 3. Modular design

##### Swiss type turning lathe: (Fig. 5, top)

Series 161 –Form knurling  
Series 162 –Knurling up to a shoulder

##### CNC-lathe: (Fig. 5, bottom)

Series 161 –Form knurling  
Series 162 –Knurling up to a shoulder




Fig. 5: Change jaws




Fig. 6: Distance A1

#### 4. Presetting of the tool

For adjustment of the working area, distance A1 must be defined first (Fig. 6).

This value can be determined according to the following calculation:

**Distance A1 = desired finished diameter of the workpiece – nominal pitch of the knurling wheel**

Example: Desired workpiece diameter = 17 mm, pitch 1.2 mm  
Distance A1 = 17 mm – 1.2 mm = 15.8 mm

Caution! This calculation only applies for a 90° flank angle!

Unscrew both Allen screws (Fig. 1, pos. 7; Fig. 2, pos. 9; Fig. 3, pos. 7; Fig. 4, pos. 10) and adjust the jaws (Fig. 1, pos. 2 + 3; Fig. 2, pos. 3 + 4; Fig. 3, pos. 2 + 3; Fig. 4, pos. 3 + 4) with the adjustment spindle (Fig. 1, pos. 5; Fig. 2, pos. 7; Fig. 3, pos. 5; Fig. 4, pos. 8). A calliper gauge is useful for measuring the distance. After adjustment of the working range, re-tighten the Allen screws.

#### 7. Feed rate in X direction

Move with the tool and the pre-adjusted working area A1 in the component in the X-direction to the workpiece zero point until the diameter of the two knurling wheels are aligned with the workpiece diameter (Fig. 10). Then the limit position of the setting is reached. The feed rate must be observed during the process. After reaching the limit position, the dwell time of the tool should be between 3 and 10 revolutions of the workpiece. Then disengage the tool from the engagement.

#### 8. Feed rate in Z direction

With movement in the axial direction, first move to the workpiece zero point (see chapter 7, Feed rate in X direction) and move parallel to the axis in the Zdirection after reaching the limit position until the desired knurl width is reached. After the limit position is reached, the dwell time should be 3 to 10 revolutions. Then disengage the tool from the engagement. For guideline values for feed rate and cutting speed, please refer Chapter 12, Table 5.




Fig. 10: Limit position during knurling

#### 10. Manufacturer's recommendations

Axle pins (Fig. 1, pos. 4; Fig. 2, pos. 8) and hinge pins (Fig. 3, pos. 6; Fig. 4, pos. 9), collar studs (Fig. 2+4, pos. 5) and races (Fig. 3, pos. 4; Fig. 4, pos. 7) should be replaced after a reasonable number of cycles, no later than upon appearance of significant wear or deviating process parameters. The slot of the jaws must also be inspected for wear or widening. An adequate flow of coolant or cutting oil is recommended!

#### 11. Troubleshooting

##### Problem: Reason / Cause: Solution:

The knurled profile is not completely formed, surface on the tooth tip	– The profile depth setting is not correct – Radial adjustment not down to limit depth	– Adjust distance A1 as specified in chapter 4 – Move in X-direction to workpiece zero point (see chapter 7)
The profile has a double knurling	– Feed rate incorrect – Profile depth too large – Dwell time in the engagement too long	– Adjust feed rate according to chapter 12 (see Table 5) – Correct the distance as specified in chapter 4 – Dwell time should be between 3 and 10 revolutions of the workpiece
Irregular profile form	Knurling wheels are uneven in the engagement due to deficient assembly of the knurling jaws	Check the adjustment of the curling jaws as specified in chapter 4
Spangle collets on the profile	– Dwell time of the tool in the engagement too long	– Dwell time should be between 3 and 10 revolutions of the workpiece
Excessive material distortion at knurling end (axial)	– Feed rate value incorrect – Profile depth is not correct – Material flow not favourable	– Adjust feed rate as specified in chapter 12 – Adjust distance as specified in chapter 4 – Use of rollers with 60° chamfer
The finished diameter of the workpiece is too small	Adjustment depth too large, overpressure on the profile	– Adjust distance as specified in chapter 4 – Observe material distortion as specified in chapter 13
– Overpressure on the profile – Diameter reduction at the beginning of the knurling	– Depth adjustment too large – Incorrect approach position / setting outside of the workpiece	– Correct distance A1 as specified in chapter 4 – Setting must take place in the component (observe chapter 7)

Table 4: Troubleshooting